

Storedahl Daybreak Mine Groundwater and River Water Level Fluctuations




Figure 3-19: Fluctuations in groundwater elevations in piezometers PZ-2, PZ-3, the irrigation well and in the river stage measured from November 2000 through December 2001